



Quick Links

Over-the-Rhine

Fountain Square

CEF & CNMF

HOME : ABOUT 3CDC : NEWSROOM : ECONOMIC INCLUSION : CONTACT US

Fountain Square District

Construction Photos - Week of February 20th

Fountain Square Plaza and Garage Improvements

Fountain Square District Development Projects

Downtown Marketing Materials

Information Archives

Construction Photo Archive

Progress for February 20th

- Below-grade garage repairs continued.
- Major structural repair work is on-going.
- Phase III of demolition has begun.
 - 5th Street has been temporarily closed to allow for repairs to the below grade garage. [Click here for more information.](#)



Workers prepare the garage for structural concrete repairs



Overhead view of demolition work on 5th Street



Closer view of demolition on 5th Street



Street level view of work on 5th Street



Demolition of the curb along 5th Street



Underground pipes exposed in order to be shutoff during demolition
Photos from previous updates

[HOME](#) : [ABOUT 3CDC](#) : [NEWSROOM](#) : [ECONOMIC INCLUSION](#) : [CONTACT US](#)

Copyright ©2005 3CDC. All Rights Reserved. Privacy Policy
Powered by editspot.