



Quick Links

Over-the-Rhine

Fountain Square

CEF & CNMF

HOME : ABOUT 3CDC : NEWSROOM : ECONOMIC INCLUSION : CONTACT US

Fountain Square District

Construction Photos - Week of October 3rd

Fountain Square Plaza and Garage Improvements

Fountain Square District Development Projects

Downtown Marketing Materials

Information Archives

Construction Photo Archive



The flagpole has been completely removed from the Square.



All the salvagable peices of the Fountain has been removed.



Workers remove granite slabs from the stage.



Granite slabs removed.



Work begins to remove steel support structure from the stage.



Excavation on the base of the Westin Skywalk stairs.

[Click Here to View Photos From Previous Updates](#)

[HOME](#) : [ABOUT 3CDC](#) : [NEWSROOM](#) : [ECONOMIC INCLUSION](#) : [CONTACT US](#)

Copyright ©2005 3CDC. All Rights Reserved. Privacy Policy
Powered by editspot.